

# Spruce & Stow

Before / After Photo Report

(719) 497-5509  
spruceandstow.com

## Job information

Address: Sample unit (staged)

Job #: SAMPLE-0001

Client / Owner: Example Property Co. (fictional)

Service type: Move-out reset

Service date: [shoot date]

Report date: [shoot date]

## Photos

BEFORE 1 · Kitchen  
[staged photo]

Items left on counters and in the open cabinet.

AFTER 1 · Kitchen  
[staged photo]

Counters cleared and wiped, cabinet emptied.

BEFORE 2 · Living room  
[staged photo]

Boxes and bags left behind, nail holes in the wall.

AFTER 2 · Living room  
[staged photo]

Items hauled off, floor swept, small nail holes filled.

BEFORE 3 · Hallway  
[staged photo]

Smoke detector chirping, HVAC filter dirty.

AFTER 3 · Hallway  
[staged photo]

Detector battery replaced, new filter dated.

## Summary of work completed (example)

Hauled away the left-behind items, which were photographed and logged first. Swept and wiped all surfaces, filled small nail holes, replaced the smoke detector battery and HVAC filter, and replaced 2 burned-out bulbs.

**Follow-up:** Example only. The owner might be advised to have a dripping faucet checked by a licensed plumber.

## Sign-off

Crew lead: \_\_\_\_\_ Date: \_\_\_\_\_

Client rep: \_\_\_\_\_ Date: \_\_\_\_\_